

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

*Various Routes
OVD SIN STR REP & REPL 2007-9
Various Counties
Sheet 31 of 50
Contract Number 44933*

*District 6
Schedule of Locations for Truss Repair & Replacement*

Location No.:	6-01	State I.D. No.:	6S075I072L004.9		
County:	Pike	Route:	I-72	M.P.:	4.9
		Direction:	WB		
Description of Work	Unit	Quantity			
REMOVE OVERHEAD SIGN STRUCTURE-SPAN	EACH	1.00			
OVERHEAD SIGN STRUCTURE-SPAN TYPE II-A	FOOT	104.00			
REMOVE & REINSTALL SIGN PANEL	SQ FT	468.00			
REMOVE & REINSTALL WALKWAY	FOOT	59.00			
REPAIR HANDRAIL LOCKING PIN CONNECTION	EACH	6.00			
FURNISH & INSTALL SAFETY CHAIN	EACH	2.00			
FURNISH & INSTALL METAL SCREEN	EACH	4.00			
DISCONNECT / RECONNECT ELECTRIC SERVICE	EACH	1.00			
REPLACE/TIGHTEN CLIP PER SIGN	EACH	1.00			
This structure is being downsized from a Type IV truss to a Type II truss.					