



- WIRING MODIFICATIONS:**
- A) IF SIGN IS NOT A FED THRU;
 - 1) REMOVE ALL WIRING FROM LOWER HANDHOLE OR JUNCTION BOX TO LUMINAIRES. (LOAD SIDE)
 - 2) CAP LINE SIDE OF WIRES.

 - B) IF SIGN IS USED AS A MID CIRCUIT TAP;
 - 1) REMOVE ALL WIRING FROM LOWER HANDHOLE OR JUNCTION BOX TO LUMINAIRES. (LOAD SIDE)
 - 2) RESPLICE LINE SIDE CABLES TO MAINTAIN CIRCUIT CONTINUITY.

NOTE:
 1. CONTRACTOR TO COORDINATE WITH IDOT ELECTRIC MAINTENANCE CONTRACTOR PRIOR TO PERFORMING ANY WORK.

MODEL: Default
 FILE NAME: p:\uplanroom.dwt
 PROJECTS\DOT\Documents\DOT_Offices\District_1\Projects\DH5422\31CAD\Drawn\CAD\sheet\sheet10.dgn

USER NAME = footemj	DESIGNED -	REVISED -
	DRAWN -	REVISED -
PLOT SCALE = 50.0000 ' / in.	CHECKED -	REVISED -
PLOT DATE = 4/19/2019	DATE - 10-16-14	REVISED -

**STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION**

**REMOVAL OF ELECTRICAL LIGHTING FROM SIGN STRUCTURE
 SHEET 1 OF 2 SPAN TYPE**

SCALE: NONE SHEET 1 OF 2 SHEETS STA. TO STA.

F.A. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
BE-610		CONTRACT NO.		
ILLINOIS FED. AID PROJECT				