

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
326		LIVINGSTON	354	347
STA. TO STA.				
FED. ROAD DIST. NO.			ILLINOIS FED. AID PROJECT	
*(123,123)RS-3, (124)RS-5, (123)BR-3				

FOR INFORMATION ONLY

The Subsurface Utility Engineering Company
 449 Munroe Falls Road
 Tallmadge, OH 44278
 (330) 794-4455

So-Deep Test Hole Certification Form
 © So-Deep 1988, 1991
 Condition of paving prior to work: NO PAVING

City, County, State: FORREST, LIVINGSTON CO., IL
 Gen. Loc.: FRONT OF PAN CLUB BAR, CENTER ST.
 Recorded Size/Material/Type: 4" C.I. WATER LINE
 Foreman/Truck/Form By: J. HENRY / 221 / J. HENRY

Control # SBM0234
 Test Hole # 17
 Plan Scale 1" = 20'
 Sheet # 48
 Proposed GRADE CHANGE
 Date AUGUST 17, 2007

B.M. 1 Elev. = 688.39'
 IS GIVEN
 Description: (BM#) CHS "1" FOUND, ON E SIDE OF CONC. MH, 41' RT OF CL STA 1247+00, CENTER ST.

B.M. 2 Elev. = 688.26'
 IS GIVEN
 Description: CHS "X" IN RIM OF BM#, 40.8' LT OF CL STA 1245+34.93, CENTER ST.

SO-DEEP will attempt to use the BM# if most applicable to your design. If necessary, data differ by more than .05', resulting differences could cause design conflicts.

Benchmarks check BY 0.01'
 Elevations are referenced to B.M.#2

Recorded Size/Type of utility WAS FOUND

There WERE NOT additional utilities in the test hole.
 The utility WAS in good condition.
 Paving Thickness and type NO PAVING
 Color of ribbon installed BLUE
 Soil Type MOIST BROWN
 Field Condition GRASS RW
 T.H. tied to PEG

4" C.I. WATER LINE
 Size/Material/Type
 Portion of pipe exposed for O.D. measurement:
 FULL
 Remarks: NONE

Existing Grade of GRASS RW
 Survey Mark PEG (set by SO-DEEP) Elev. 687.76'
 Actual field measurement by ruler (not calculated)
 Surveyed Elev. 681.82'
 Top Util/Struc.
 Surveyed Elev. (if required)

TH DUG 40.6'± RT OF CL STA 1246+30.6±, CENTER STREET

Performing out-of-sight work...with vision™
 Note: To eliminate mistakes and check this work, So-Deep suggests you make and plot all dimensions onto the plans and review all elevations carefully. So-Deep is responsible only for information shown on our forms.

The Subsurface Utility Engineering Company
 449 Munroe Falls Road
 Tallmadge, OH 44278
 (330) 794-4455

So-Deep Test Hole Certification Form
 © So-Deep 1988, 1991
 Condition of paving prior to work: NO PAVING

City, County, State: FORREST, LIVINGSTON CO., IL
 Gen. Loc.: JUST S OF PAN CLUB BAR, CENTER ST.
 Recorded Size/Material/Type: 4" WSTL GAS LINE
 Foreman/Truck/Form By: J. HENRY / 221 / J. HENRY

Control # SBM0234
 Test Hole # 18
 Plan Scale 1" = 20'
 Sheet # 49
 Proposed GRADE CHANGE
 Date AUGUST 17, 2007

B.M. 1 Elev. = 688.39'
 IS GIVEN
 Description: (BM#) CHS "1" FOUND, ON E SIDE OF CONC. MH, 41' RT OF CL STA 1247+00, CENTER ST.

B.M. 2 Elev. = 688.26'
 IS GIVEN
 Description: CHS "X" IN RIM OF BM#, 40.8' LT OF CL STA 1245+34.93, CENTER ST.

SO-DEEP will attempt to use the BM# if most applicable to your design. If necessary, data differ by more than .05', resulting differences could cause design conflicts.

Benchmarks check BY 0.01'
 Elevations are referenced to B.M.#2

Recorded Size/Type of utility WAS FOUND

There WERE NOT additional utilities in the test hole.
 The utility WAS in good condition.
 Paving Thickness and type NO PAVING
 Color of ribbon installed YELLOW
 Soil Type MOIST BROWN
 Field Condition GRASS RW
 T.H. tied to PEG

4" WSTL GAS LINE
 Size/Material/Type
 Portion of pipe exposed for O.D. measurement:
 FULL
 Remarks: NONE

Existing Grade of GRASS RW
 Survey Mark PEG (set by SO-DEEP) Elev. 687.76'
 Actual field measurement by ruler (not calculated)
 Surveyed Elev. 684.72'
 Top Util/Struc.
 Surveyed Elev. (if required)

TH DUG 36.2'± RT OF CL STA 1246+00.6±, CENTER STREET

Performing out-of-sight work...with vision™
 Note: To eliminate mistakes and check this work, So-Deep suggests you make and plot all dimensions onto the plans and review all elevations carefully. So-Deep is responsible only for information shown on our forms.

The Subsurface Utility Engineering Company
 449 Munroe Falls Road
 Tallmadge, OH 44278
 (330) 794-4455

So-Deep Test Hole Certification Form
 © So-Deep 1988, 1991
 Condition of paving prior to work: NO PAVING

City, County, State: FORREST, LIVINGSTON CO., IL
 Gen. Loc.: JUST S OF PAN CLUB BAR, CENTER ST.
 Recorded Size/Material/Type: 4" C.I. WATER LINE
 Foreman/Truck/Form By: J. HENRY / 221 / J. HENRY

Control # SBM0234
 Test Hole # 19
 Plan Scale 1" = 20'
 Sheet # 48
 Proposed GRADE CHANGE
 Date AUGUST 20, 2007

B.M. 1 Elev. = 688.39'
 IS GIVEN
 Description: (BM#) CHS "1" FOUND, ON E SIDE OF CONC. MH, 41' RT OF CL STA 1247+00, CENTER ST.

B.M. 2 Elev. = 688.16'
 IS GIVEN
 Description: CHS "X" IN RIM OF BM#, 30.4' RT OF CL STA 1250+08.77, CENTER ST.

SO-DEEP will attempt to use the BM# if most applicable to your design. If necessary, data differ by more than .05', resulting differences could cause design conflicts.

Benchmarks check BY 0.01'
 Elevations are referenced to B.M.#2

Recorded Size/Type of utility WAS FOUND

There WERE NOT additional utilities in the test hole.
 The utility WAS in good condition.
 Paving Thickness and type NO PAVING
 Color of ribbon installed BLUE
 Soil Type MOIST BROWN
 Field Condition GRASS RW
 T.H. tied to PEG

4" C.I. WATER LINE
 Size/Material/Type
 Portion of pipe exposed for O.D. measurement:
 FULL
 Remarks: NONE

Existing Grade of GRASS RW
 Survey Mark PEG (set by SO-DEEP) Elev. 687.66'
 Actual field measurement by ruler (not calculated)
 Surveyed Elev. 682.85'
 Top Util/Struc.
 Surveyed Elev. (if required)

TH DUG 40.0'± RT OF CL STA 1247+99.0±, CENTER STREET

Performing out-of-sight work...with vision™
 Note: To eliminate mistakes and check this work, So-Deep suggests you make and plot all dimensions onto the plans and review all elevations carefully. So-Deep is responsible only for information shown on our forms.

REVISIONS		ILLINOIS DEPARTMENT OF TRANSPORTATION	
NAME	DATE		
		SCALE: VERT. HORIZ.	DRAWN BY
		DATE	CHECKED BY