

Rubblization Pavement and Subsurface Investigation - Southbound FAI 57

Section: (41-3-1)RS-1;(41-8)RS-2

Contract 78276

Station	Location					Thickness, in.			Subbase condition			Subgrade IBV					Soil Information							
	PS	3I	2I	DI	DS	AC Overlay	PCC	Subbase	Sound	SI Deter	Deter	0-6"	6-12"	12-18"	18-24"	24-30"	Classification	Sand	Silt	Clay	LL	PI	% H ₂ O	
877+00			X			3 3/4	8 1/4	3	BAM			17.0	12.0	7.0	8.5									
" "	X					14 1/2						14.0	29.0	20.0	17.0									
867+00			X			3 3/4	8 1/4	3		BAM		16.0	30.0	30.0										
" "	X					13 3/4						7.0	23.0	30.0	30.0									
857+00			X			3 3/4	8	3 3/4	BAM			30.0												
" "	X					12 1/2						5.5	30.0											
847+00			X			3 3/4	8	4 1/4	BAM			7.0	7.0	4.0	7.0		CLAY A7-6(19)	26	40	34	44.9	27.7	18	
" "	X					11 1/2						5.5	4.0	7.0	7.0	7.0								
837+00			X			3	8 1/2	3 1/2	BAM			12.0	8.5	7.0	10.0									
" "	X					13 1/2						7.0	4.0	5.5	7.0	8.5								