

Rubblization Pavement and Subsurface Investigation - Westbound FAI 64

Section: (41-3-1)RS-1;(41-8)RS-2

Contract 78276

Station	Location					Thickness, in.			Subbase condition			Subgrade IBV					Soil Information							
	PS	3I	2I	DI	DS	AC Overlay	PCC	Subbase	Sound	SI Deter	Deter	0-6"	6-12"	12-18"	18-24"	24-30"	Classification	Sand	Silt	Clay	LL	PI	% H ₂ O	
2403+00			X			3 3/4	8 1/2	3 1/2			BAM	10.0	14.0	12.0	10.0									
" "	X					10 1/4	4 1/2				PCC	8.5	16.0	7.0	8.5									
2396+00			X			3 1/2	8 1/2	3 1/2			BAM	5.5	7.0	7.0	8.5									
" "	X					15						5.5	7.0	8.5	7.0									
2384+00			X			3 3/4	8 1/4	4			BAM	7.0	14.0	17.0	18.0		SICI A-6(12)	10	67	23	33.2	14.4	21	
" "	X					12 1/2						7.0	21.0	12.0	12.0	8.5								
2375+00			X			2 3/4	8 3/4	3 1/2			BAM	10.0	10.0	5.5	10.0									
" "	X					14						8.5	10.0	23.0	30.0									
2365+00			X			2 1/2	8 3/4	3			BAM	10.0	7.0	5.5	8.5									
" "	X					12 1/2						5.5	5.5	8.5	12.0	12.0								
2355+00			X			4 1/4	7 3/4	4			BAM	8.5	12.0	7.0	7.0									
" "	X					11						8.5	5.5	10.0	10.0	8.5								