



Graffiti Removal
 Repair, I.D.
 132 22 SF
 Repair Area Sq. Ft.
GRAFFITI REMOVAL

HL 12 Crack Length (Feet)
 Crack Width (Inches)
CRACKS < 1/16"
 Hairline Cracks (HL) or
 Cracks < 1/16" not to be Sealed.

REPAIRS LIST - SOUTH ABUTMENT

I.D.	Description	Pay Item	Units	Quantity
132	Beams 1-7, Each Web Face	Graffiti Removal	SQ. YD.	233.3

DESIGNED -	EXAMINED	DATE
CHECKED -	ENGINEER OF STRUCTURAL SERVICES	
DRAWN Rod	PASSED	ENGINEER OF BRIDGES AND STRUCTURES
CHECKED MNM		

STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION

REPAIRS TO - SOUTH ABUTMENT
 STRUCTURE NO. 060-0255

SHEET NO. 16 OF 48 SHEETS

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
304	100B-IDS-1	MADISON	58	26
CONTRACT NO. 76E73			ILLINOIS FED. AID PROJECT	