




SE CORNER GARDEN AT 79TH STREET



DETAIL A




INSPECTION PIPE, 4"




CUT NOTCHES IN INSPECTION PIPE


DRAIN SLEEVE ELEVATION



SECTION A-A



SECTION B-B



SECTION C-C

REVISIONS	
NAME	DATE