


The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)
 AASHTO Classifications are based on visual classifications unless otherwise noted BBS, form 137 (Rev. 8-99)



The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)
 AASHTO Classifications are based on visual classifications unless otherwise noted BBS, form 137 (Rev. 8-99)

REVISIONS

Carlson Business Center I
 100 Luntz Court, Suite 1
 Collinsville, Illinois 62234
 Phone: 618 246-2200
 Fax: 618 246-2200
 e-mail: info@scie.com
 web-site: www.scie.com

GATES ASSOCIATES
 Consulting Engineers

ALTON, ILLINOIS
 PEDESTRIAN OVERPASS AT LANGDON ST.

BORING LOGS
ALTON PEDESTRIAN WALKWAY OVER
UNION PACIFIC RAILROAD, NORFOLK
SOUTHERN RAILROAD AND US ROUTE 67
SECTION 06-00224-00-BR
MADISON COUNTY
STA. 2+42.54
STRUCTURE NO. 060-6111

DWG. NO.	S23
6111-23-BORESHT1.DGN	
REF. BK.	PG.
JOB NO.	
DSN. BY:	NEL
DWN. BY:	NEL
CHK. BY:	JGS
DATE:	1/9/07
SCALE:	
SHEET	43 OF 54