

VERIFIED UTILITY INFORMATION

TEST HOLE #	SIZE & TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
1	36" W	1812069.68	1168292.19	582.09'	4.45'	586.54'	UTILITY QUALITY "A"
2	36" W	1812630.15	1168300.42	580.85'	4.71'	585.56'	UTILITY QUALITY "A"
3	36" W	1813244.62	1168286.40	589.78'	5.31'	595.09'	UTILITY QUALITY "A"
4	N/A W	1814420.43	1168246.77	592.22'	5.99'	598.21'	UTILITY QUALITY "B"
5	N/A W	1812382.44	1168288.95	575.85'	4.51'	580.36'	UTILITY QUALITY "B"
6	36" W	1812545.22	1168281.90	577.32'	4.62'	581.94'	UTILITY QUALITY "A"
7	36" W	1812879.15	1168289.32	588.71'	5.00'	593.71'	UTILITY QUALITY "A"
8	12" W	1813749.10	1168202.75	592.20'	4.57'	596.77'	UTILITY QUALITY "A"
8A	3" UNK	1813749.06	1168202.63	594.47'	2.30'	596.77'	UTILITY QUALITY "A"
9	12" W	1813251.11	1168220.76	590.71'	5.07'	595.78'	UTILITY QUALITY "A"
10	36" W	1812964.22	1168292.21	591.33'	3.61'	594.94'	UTILITY QUALITY "A"
11	12" W	1812970.94	1168230.39	590.22'	4.94'	595.16'	UTILITY QUALITY "A"
12	12" W	1812074.15	1168216.50	589.67'	1.91'	591.58'	UTILITY QUALITY "A"
13	12" W	1812808.20	1168222.58	591.40'	2.42'	593.82'	UTILITY QUALITY "A"
14	12" W	1814678.13	1168237.91	592.26'	3.27'	595.53'	UTILITY QUALITY "A"
15	36" W	1814674.17	1168228.66	591.09'	5.92'	597.01'	UTILITY QUALITY "A"
16	12" W	1814673.36	1168220.66	592.74'	4.33'	597.07'	UTILITY QUALITY "A"
17	12" W	1815159.11	1168208.11	583.02'	4.36'	587.38'	UTILITY QUALITY "B"
18	N/A W	1815158.88	1168193.91	580.36'	7.21'	587.57'	UTILITY QUALITY "B"
19	N/A W	1815314.96	1168202.50	583.29'	5.00'	588.29'	UTILITY QUALITY "B"
20	N/A W	1815308.00	1168186.81	582.07'	5.49'	587.56'	UTILITY QUALITY "B"
21	N/A W	1815485.43	1168196.72	583.06'	4.69'	587.75'	UTILITY QUALITY "B"
22	N/A W	1815486.52	1168180.55	582.67'	4.75'	587.42'	UTILITY QUALITY "B"
23	N/A W	1815576.67	1168177.56	583.40'	4.22'	587.62'	UTILITY QUALITY "B"
24	N/A W	1815588.26	1168200.76	585.86'	4.78'	590.64'	UTILITY QUALITY "B"
25	36" W	1815598.65	1168193.01	583.91'	4.50'	588.41'	UTILITY QUALITY "A"
26	N/A W	1815546.45	1168194.08	582.59'	5.32'	587.91'	UTILITY QUALITY "B"
27	36" W	1814996.76	1168216.62	583.83'	5.81'	589.64'	UTILITY QUALITY "A"
28	12" W	1814259.37	1168184.28	592.54'	5.22'	597.76'	UTILITY QUALITY "A"
29	12" W	1812670.37	1168206.17	589.81'	2.10'	591.91'	UTILITY QUALITY "A"
30	N/A W	1814419.45	1168238.82	592.31'	5.68'	597.99'	UTILITY QUALITY "B"
31	12" W	1812089.05	1168323.50	586.70'	1.99'	588.69'	UTILITY QUALITY "A"
32	12" W	1812330.83	1168317.88	579.49'	2.47'	581.96'	UTILITY QUALITY "A"
33	12" W	1813236.43	1168303.40	590.19'	5.39'	595.58'	UTILITY QUALITY "A"
34	36" W	1813751.44	1168267.31	591.10'	6.11'	597.21'	UTILITY QUALITY "A"

NOTES

TH #4, 19, 21, 24 & 26 - Unable to verify size & material of pipe due to excessive ground water infiltration within the excavated hole. However, by utilizing an air lance we were able to feel what is believed to be the top of a 12" water main.
 TH #5, 18, 20, 22, 23 & 30 - Unable to verify size & material of pipe due to excessive ground water infiltration within the excavated hole. However, by utilizing an air lance we were able to feel what is believed to be the top & sides of a 36" water main.
 TH #8A -Found unknown utility while excavating for water main. Appears to be a fiberglass material.
 TH #17 - Briefly exposed 12" main before excessive ground water infiltrated the excavated hole. Manual depth was taken.
 TH #34 - 36" water offset taken from centerline of 138th Street.

ABBREVIATIONS

UNK = UNKNOWN
 W = WATER

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.



Checked By: _____
 Date: _____

TBE Job No. IL09510509

DESIGNED <i>ED</i>	REVISED	
DRAWN <i>SRK</i>	REVISED	
CHECKED <i>KFS</i>	REVISED	
DATE <i>9/28/12</i>	REVISED	

**STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION**

**Ashland Ave. Broadway to Thornton Rd.
 Blue Island, IL**

SHEET NO. _____ STA. _____ TO STA. _____

F.A.U. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
2857	146-T 2 11-054-1	Cook	16	12
FED. ROAD DIST. NO. ILLINOIS			Contract No. 60P64 Job No.: 60R82	