

VERIFIED UTILITY INFORMATION

| TEST HOLE # | SIZE & TYPE | NORTHING    | EASTING     | TOP OF UTILITY | EXISTING CUT | REFERENCE GROUND ELEVATION | COMMENTS              |
|-------------|-------------|-------------|-------------|----------------|--------------|----------------------------|-----------------------|
| 53          | *18" BT     | 1865113.010 | 1175555.020 | 4.67'          | 14.33'       | 19.00'                     | SUE QUALITY LEVEL "A" |
| 54          | See Note E  | 1865117.050 | 1175555.790 | ---            | 18.59'       | 18.99'                     | CLEARANCE DEPTH ONLY  |
| 55          | *18" BT     | 1865108.400 | 1175989.320 | 9.85'          | 9.02'        | 18.87'                     | SUE QUALITY LEVEL "A" |
| 55A         | 24" SAN     | 1865109.300 | 1175987.610 | 11.77'         | 7.10'        | 18.87'                     | SUE QUALITY LEVEL "A" |
| 56          | *36" E      | 1865136.380 | 1175984.770 | 3.20'          | 15.68'       | 18.88'                     | SUE QUALITY LEVEL "A" |
| 56A         | 24" SAN     | 1865138.320 | 1175986.600 | 11.93'         | 6.92'        | 18.85'                     | SUE QUALITY LEVEL "A" |
| 57          | *18" BT     | 1865091.120 | 1175928.050 | -5.77'         | 7.13'        | 1.36'                      | SUE QUALITY LEVEL "A" |
| 58          | *36" E      | 1865105.640 | 1175928.120 | -4.59'         | 6.03'        | 1.44'                      | SUE QUALITY LEVEL "A" |
| 59          | *36" E      | 1865104.390 | 1175856.480 | -4.90'         | 7.41'        | 2.51'                      | SUE QUALITY LEVEL "A" |
| 60          | *18" BT     | 1865090.480 | 1175856.950 | -5.29'         | 7.65'        | 2.36'                      | SUE QUALITY LEVEL "A" |
| MAN HOLE #  | TYPE        | NORTHING    | EASTING     | TOP OF UTILITY | EXISTING CUT | REFERENCE MH RIM ELEVATION | COMMENTS              |
| 61          | Telephone   | 1863240.510 | 1175610.790 | *1.41'         | 19.13'       | 20.54'                     | SUE QUALITY LEVEL "A" |
| TEST HOLE # | SIZE & TYPE | NORTHING    | EASTING     | TOP OF UTILITY | EXISTING CUT | REFERENCE GROUND ELEVATION | COMMENTS              |
| 62          | *48" E      | 1876425.900 | 1176044.730 | -6.88'         | 3.44'        | -3.44'                     | SUE QUALITY LEVEL "A" |
| 63          | *48" E      | 1876427.860 | 1176056.140 | -4.87'         | 4.14'        | -0.73'                     | SUE QUALITY LEVEL "A" |
| 64          | *48" E      | 1876443.770 | 1176104.400 | 4.13'          | 8.39'        | 12.52'                     | SUE QUALITY LEVEL "A" |
| 65          | *48" E      | 1863237.110 | 1175774.930 | -1.66'         | 4.62'        | 2.96'                      | SUE QUALITY LEVEL "A" |
| 66          | *48" E      | 1841495.350 | 1177598.790 | 8.42'          | 7.24'        | 15.66'                     | SUE QUALITY LEVEL "A" |
| 67          | *48" E      | 1852792.550 | 1177384.230 | -10.35'        | 4.37'        | -5.98'                     | SUE QUALITY LEVEL "A" |
| 68          | *48" E      | 1852792.730 | 1177375.900 | -8.91'         | 4.03'        | -4.88'                     | SUE QUALITY LEVEL "A" |
| 69          | *48" E      | 1841506.530 | 1177600.310 | 7.60'          | 8.15'        | 15.75'                     | SUE QUALITY LEVEL "A" |
| 70          | *48" E      | 1852792.330 | 1177435.710 | -12.58'        | 5.65'        | -6.93'                     | SUE QUALITY LEVEL "A" |
| 71          | *28" E      | 1841906.380 | 1177641.010 | 12.54'         | 3.46'        | 16.00'                     | SUE QUALITY LEVEL "A" |
| 72          | *48" E      | 1852791.510 | 1177336.410 | 1.83'          | 7.76'        | 9.59'                      | SUE QUALITY LEVEL "A" |
| 73          | *48" E      | 1876423.560 | 1175920.080 | -12.48'        | 8.82'        | -3.66'                     | SUE QUALITY LEVEL "A" |
| 74          | *48" E      | 1863227.820 | 1175613.390 | 8.97'          | 11.23'       | 20.20'                     | SUE QUALITY LEVEL "A" |
| 75          | *48" E      | 1841508.250 | 1177677.360 | -7.19'         | 4.61'        | -2.58'                     | SUE QUALITY LEVEL "A" |
| 76          | *48" E      | 1841498.000 | 1177684.360 | -7.65'         | 4.53'        | -3.12'                     | SUE QUALITY LEVEL "A" |
| 77          | *48" E      | 1841492.150 | 1177692.100 | -7.95'         | 7.02'        | -0.93'                     | SUE QUALITY LEVEL "A" |

VERIFIED UTILITY INFORMATION

| TEST HOLE # | SIZE & TYPE  | NORTHING    | EASTING     | TOP OF UTILITY | EXISTING CUT | REFERENCE GROUND ELEVATION | COMMENTS              |
|-------------|--------------|-------------|-------------|----------------|--------------|----------------------------|-----------------------|
| 78          | *48" E       | 1841506.430 | 1177692.980 | -8.94'         | 7.98'        | -0.96'                     | SUE QUALITY LEVEL "A" |
| 79          | *48" E       | 1841510.920 | 1177755.020 | -9.22'         | 10.16'       | 0.94'                      | SUE QUALITY LEVEL "A" |
| 80          | SEE NOTE E   | 1841493.150 | 1177753.350 | ---            | 7.88'        | 1.00'                      | CLEARANCE DEPTH ONLY  |
| 81          | SEE NOTE E   | 1852793.298 | 1177394.984 | -11.95'        | 4.69'        | -7.26'                     | SUE QUALITY LEVEL "A" |
| 82          | *48" E       | 1863234.932 | 1175653.520 | -0.86'         | 7.66'        | 6.80'                      | SUE QUALITY LEVEL "A" |
| 83          | *48" E       | 1863235.070 | 1175661.514 | -1.64'         | 5.94'        | 4.31'                      | SUE QUALITY LEVEL "A" |
| 84          | 36" W        | 1839944.740 | 1178217.900 | -5.13'         | 2.96'        | -2.17'                     | SUE QUALITY LEVEL "A" |
| 85          | 36" W        | 1839889.120 | 1178193.100 | -13.96'        | 8.61'        | -5.35'                     | SUE QUALITY LEVEL "A" |
| 86          | 36" W        | 1839415.910 | 1178025.040 | -1.59'         | 3.05'        | 1.46'                      | SUE QUALITY LEVEL "A" |
| 87          | 16" UNK      | 1839528.800 | 1178066.220 | -3.15'         | 10.03'       | 6.88'                      |                       |
| 88          | 24" TEL      | 1839826.880 | 1178316.500 | -6.59'         | 7.19'        | 0.60'                      | SUE QUALITY LEVEL "A" |
| 89          | SEE NOTE TEL | 1839836.600 | 1178319.800 | -5.49'         | 5.98'        | 0.49'                      |                       |
| 90          | SEE NOTE TEL | 1839793.600 | 1178305.180 | ---            | 13.65'       | 0.40'                      | CLEARANCE DEPTH ONLY  |
| 91          | 24" TEL      | 1844059.140 | 1177578.380 | 13.58'         | 2.89'        | 16.47'                     | SUE QUALITY LEVEL "A" |
| 92          | 36" W        | 1839745.710 | 1178145.690 | -18.57'        | 9.32'        | -9.25'                     | SUE QUALITY LEVEL "A" |
| 93          | 24" BT       | 1844060.690 | 1177635.830 | -6.44'         | 7.25'        | 0.81'                      | SUE QUALITY LEVEL "A" |
| 94          | 24" BT       | 1844060.680 | 1177625.600 | -3.42'         | 6.54'        | 3.12'                      | SUE QUALITY LEVEL "A" |
| 95          | 16" W        | 1839246.750 | 1178863.580 | -6.12'         | 3.82'        | -2.30'                     | SUE QUALITY LEVEL "A" |
| 96          | SEE NOTE W   | 1838928.400 | 1178898.950 | ---            | 10.80'       | -1.39'                     | CLEARANCE DEPTH ONLY  |
| 97          | 18" BT       |             |             |                | 6.12'        |                            | NOT SURVEYED          |
| 98          | 20" BT       | 1841825.960 | 1177936.970 | 6.82'          | 8.10'        | 14.92'                     | SUE QUALITY LEVEL "A" |
| 99          | 36" W        | 1874261.670 | 1175871.220 | -1.10'         | 3.83'        | 2.73'                      | SUE QUALITY LEVEL "A" |
| 100         | 36" W        | 1874261.650 | 1175880.560 | 1.35'          | 3.90'        | 5.25'                      | SUE QUALITY LEVEL "A" |
| 101         | 36" W        | 1874245.970 | 1175540.410 | -2.86'         | 4.69'        | 1.83'                      | SUE QUALITY LEVEL "A" |
| 102         | 36" W        | 1874245.820 | 1175531.730 | -0.50'         | 4.56'        | 4.06'                      | SUE QUALITY LEVEL "A" |
| 103         | 36" W        | 1874244.500 | 1175483.430 | 11.43'         | 4.34'        | 15.77'                     | SUE QUALITY LEVEL "A" |
| 104         | SEE NOTE W   | 1874262.410 | 1175925.500 | 13.62'         | 3.18'        | 16.80'                     | SUE QUALITY LEVEL "A" |
| 105         | 36" W        | 1874245.260 | 1175675.910 | -2.22'         | 2.72'        | 0.50'                      | SUE QUALITY LEVEL "A" |
| 106         | 18" BT       | 1847350.430 | 1177491.230 | -0.33'         | 8.75'        | 8.42'                      | SUE QUALITY LEVEL "A" |
| 107         | SEE NOTE BT  | 1847365.000 | 1177775.620 | ---            | 16.79'       | 7.85'                      | CLEARANCE DEPTH ONLY  |
| 108         | 24" BT       | 1844064.680 | 1177880.760 | 6.97'          | 9.52'        | 16.49'                     | SUE QUALITY LEVEL "A" |
| 109         | 36" W        | 1874248.230 | 1175729.730 | -1.93'         | 3.19'        | 1.26'                      | SUE QUALITY LEVEL "A" |

TBE Project Information

\* Size given is duct width only.  
 TH#54 TBE could not reach utility due to depth, Clearance given.  
 MH#61 Man Hole elevation to top of phone cables exiting man hole.  
 TH#80 Could not expose utilities due to extremely hard clay. Clearance depth of 7.88' given.  
 TH#81 Appears to be a 34" poured in place concrete cap over CTA conduit.  
 TH#87 found a 16" pipe but was unable to see it due to water table. Probed another 3' down past pipe, unable to find 36" w/m electronic Depth 24'  
 TH#89 Utility not exposed due to excessive water in hole.  
 TH#90 Utility not exposed, clearance depth of 13.65'.  
 TH#96 Utility not exposed, clearance depth of 10.80'.  
 TH#97 Reference point destroyed by construction crews before survey could be completed. Material was unidentifiable.  
 TH#104 Concrete cap poured over utility.  
 TH#107 Utility not exposed, clearance depth of 16.79'.

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.

Illinois Department of Transportation

I-90 /94 (NB & SB of Dan Ryan Expressway)  
 Chicago-Cook County  
 Sec No: (2122-921 PT1) R, (2021-922 PT1,2)  
 Contract No. 62586, 62589, 62693, 62694, 62695  
 TBE Project No.: IL09500164, 167, 168, 170, 171, 179, 180, 182, 204, 205, 206, 211, 212, 219, 221, 225, 226, 227, 228, 230, 232

| DATE    |  | BY  | DESCRIPTION                  | DATE |  | BY | DESCRIPTION | DATE |  | BY | DESCRIPTION | DATE |  | BY | DESCRIPTION |
|---------|--|-----|------------------------------|------|--|----|-------------|------|--|----|-------------|------|--|----|-------------|
| 6-15-06 |  | KLC | REMOVE QL "A" FROM TH#7 & 89 |      |  |    |             |      |  |    |             |      |  |    |             |

*J. Johnson E-9802*



VERIFIED UTILITY LOCATIONS