

PHONE 815/223-6696 *Midwest Testing Services, Inc.* SHEET 1 OF 4
 3705 Progress Boulevard Peru, Illinois 61354

BORING LOG

BORING NO. 2 PROJECT CH-3 Over the Fox River, Sheridan, Illinois
 LOCATION Centerline of Proposed Road Station 22+22
 GROUND WATER, BAR. - AAR 534.0 SEEPAGE ENCOUNTERED @ 534.0 DATE COMPLETED April 5, 1999

DEPTH ELEV.	DESCRIPTION	SAMPLE		N	Q _w T.S.F.	WC	Q _w , T.S.F.																	
		NO.	TYPE				0	1	2	3	4	5	6	7	8	9	10							
539.1	STIFF BLACK & BRONNISH BLACK SANDY CLAY LOAM	1	SS	10	1.2	-																		
536.6	MEDIUM BROWN SILTY CLAY	2	SS	12	1.6	-																		
534.1	MEDIUM BROWN FINE SAND	3	SS	19	-	-																		
	MEDIUM BROWN FINE SAND TO FINE GRAVEL	4	SS	16	-	-																		
		5	SS	18	-	-																		
		6	SS	22	-	-																		

COMMENTS: STANDARD PENETRATION BLOWS/12"
 NATURAL WATER CONTENT %

DRILLED BY Randy Safranski INSPECTOR

PHONE 815/223-6696 *Midwest Testing Services, Inc.* SHEET 2 OF 4
 3705 Progress Boulevard Peru, Illinois 61354

BORING LOG

BORING NO. 2 PROJECT CH-3 Over the Fox River, Sheridan, Illinois
 LOCATION Centerline of Proposed Road Station 22+22
 GROUND WATER, BAR. - AAR 534.0 SEEPAGE ENCOUNTERED @ 534.0 DATE COMPLETED April 5, 1999

DEPTH ELEV.	DESCRIPTION	SAMPLE		N	Q _w T.S.F.	WC	Q _w , T.S.F.																	
		NO.	TYPE				0	1	2	3	4	5	6	7	8	9	10							
524.1	DENSE BROWN FINE GRAVEL	7	SS	32	-	-																		
		8	SS	76	-	-																		
		9	SS	100	9"	-																		
		10	SS	100	2"	-																		
	VERY DENSE BROWN FINE SAND TO COARSE GRAVEL w/COBBLES	11	SS	66	-	-																		
		12	SS	56	-	-																		
		13	SS	100	1"	-																		

COMMENTS: STANDARD PENETRATION BLOWS/12"
 NATURAL WATER CONTENT %

DRILLED BY Randy Safranski INSPECTOR

PHONE 815/223-6696 *Midwest Testing Services, Inc.* SHEET 3 OF 4
 3705 Progress Boulevard Peru, Illinois 61354

BORING LOG

BORING NO. 2 PROJECT CH-3 Over the Fox River, Sheridan, Illinois
 LOCATION Centerline of Proposed Road Station 22+22
 GROUND WATER, BAR. - AAR 534.0 SEEPAGE ENCOUNTERED @ 534.0 DATE COMPLETED April 5, 1999

DEPTH ELEV.	DESCRIPTION	SAMPLE		N	Q _w T.S.F.	WC	Q _w , T.S.F.																	
		NO.	TYPE				0	1	2	3	4	5	6	7	8	9	10							
		14	SS	100	3"	-																		
		15	SS	83	-	-																		
		16	SS	100	4"	-																		
	VERY DENSE BROWN FINE TO COARSE GRAVEL w/COBBLES & BOULDERS	17	SS	61	-	-																		
		18	SS	94	-	-																		
		19	SS	87	-	-																		
		20	SS	100	2"	-																		

COMMENTS: STANDARD PENETRATION BLOWS/12"
 NATURAL WATER CONTENT %

DRILLED BY Randy Safranski INSPECTOR

PHONE 815/223-6696 *Midwest Testing Services, Inc.* SHEET 4 OF 4
 3705 Progress Boulevard Peru, Illinois 61354

BORING LOG

BORING NO. 2 PROJECT CH-3 Over the Fox River, Sheridan, Illinois
 LOCATION Centerline of Proposed Road Station 22+22
 GROUND WATER, BAR. - AAR 534.0 SEEPAGE ENCOUNTERED @ 534.0 DATE COMPLETED April 5, 1999

DEPTH ELEV.	DESCRIPTION	SAMPLE		N	Q _w T.S.F.	WC	Q _w , T.S.F.																	
		NO.	TYPE				0	1	2	3	4	5	6	7	8	9	10							
		21	SS	100	5"	-																		
		22	SS	100	1"	-																		
	VERY DENSE BROWN FINE TO COARSE GRAVEL w/COBBLES & BOULDERS	23	SS	78	-	-																		
		24	SS	100	3"	-																		
481.6		25	SS	100	2"	-																		
		26	SS	100	3"	-																		
	VERY DENSE LIGHT BROWN TO WHITE SANDSTONE	27	SS	100	1"	-																		
473.1		28	SS	100	1"	-																		

COMMENTS: STANDARD PENETRATION BLOWS/12"
 NATURAL WATER CONTENT %

DRILLED BY Randy Safranski INSPECTOR

SOIL BORING LOGS
 FAS 259 C.H. 3
 OVER FOX RIVER
 LA SALLE COUNTY
 STA. 20+15.00
 STRUCTURE NO. 050-3562

DRAWN BY: ARR	CAD: SOIL	REVISIONS		SCALE: NONE	SHEET 61
		DATE	BY		
CHECKED BY: JKC	DATE: 02/03			FILE NO.: 11174.01Y-1	OF 79