
## <u>LEGEND</u>



Limits of Removal and Disposal of Unsuitable Material for Structures, Backfill with Aggregate Subgrade Improvement.



~~Z-**~** 

## Notes:

The limits and quantities of removal and replacement of unsuitable material for structures shown are based on the boring data and may be modified by the Engineer for variable subsurface conditions encountered in the field.

See Sheet 8 of 25 for cross section limits of Removal and Disposal of Unsuitable Material for Structures and placement of Aggregate Subgrade Improvement.

V	V3 Companies of Hilinois Ltd. 7325 Janes Avenue Woodridge, IL 60517 630.724.9200 phone 630.724.9202 fax
	www.v3co.com

USER NAME =	DESIGNED - EVS	REVISED
	CHECKED - WJV	REVISED
PLOT SCALE =	DRAWN - EVS	REVISED
PLOT DATE =	CHECKED - WJV	REVISED

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	353	11-Y-A	COOK	354	259
31NOCIONE NO. 010-1200			CONTRACT	NO.	60R19
SHFFT NO. 4 OF 25 SHFFTS	TILL INDISCRED. AID PROJECT				