Illinois Department of Transportation
Division of Highways
Geotechnology, Inc

SOIL BORING LOG

Date 11/2/00

ROUTE FAP 998 DESCRIPTION Trilevel Interchange LOGGED BY BEC

SECTION 82-1 LOCATION East St. Louis, IL, SEC.7, TWP. 2N, RNG. 9W

COUNTY St. Clair DRILLING METHOD Hollow Stem Auger and Mud Rotary HAMMER TYPE Automatic Hammer

STRUCT. NO. 082-W306
Station NA

BORING NO. B-18
Station 62+26.75
Offset 21ft Right
Ground Surface Elev. 420.0 ft

Surface Water Elev. Unknown ft
Stream Bed Elev. Unknown ft

Groundwater Elev.:
First Encounter ** ft
Upon Completion ** ft
After ** Hrs. ** ft

DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)
GRAVEL, BOULDERS (continued) 299.5			
CRYSTALLINE LIMESTONE - See Rock Core Log			
-125			
-130			
289.5 End of Boring			
-135			
-140			

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)
The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)
* Rimac attempted, not measured due to sample disturbance
** Not measured due to drilling methods used
BBS, from 137 (Rev. 8-99)

Illinois Department of Transportation
Division of Highways
Geotechnology, Inc

SOIL BORING LOG

Date 11/26/01

ROUTE FAP 998 DESCRIPTION Trilevel Interchange LOGGED BY JSS

SECTION 82-1 LOCATION East St. Louis, IL, SEC. 7, TWP. 2N, RNG. 9W

COUNTY St. Clair DRILLING METHOD HSA and Mud Rotary HAMMER TYPE Automatic Hammer

STRUCT. NO. 082-W306
Station

BORING NO. B-211
Station 67+60.43
Offset 8ft Right
Ground Surface Elev. 416.8 ft

Surface Water Elev. Unknown ft
Stream Bed Elev. Unknown ft

Groundwater Elev.:
First Encounter 397.8 ft ▼
Upon Completion ** ft
After ** Hrs. ** ft

DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)
Crushed limestone GRAVEL (FILL) - 6 inches 416.3			
Dark brown, SILTY CLAY (FILL)	1		
	2		24
with crushed limestone gravel to 3 feet	3		
	2		
	2		23
-5	6		
	1		
	1		26
408.8	2		
Stiff to medium stiff, brown, SILT	2		
	5		16
-10	7		
	3		
	4		
No sample recovery in SS-5	7		
	1		
	3		25
See Gradation Test Results 401.8 -15	4		
Medium stiff, brown, SILTY LOAM	3		
	3		27
sandy clay seams from 16 to 18 feet	3		
398.6 Soft, grayish-brown, SILTY CLAY ▼	0		
-20	1		
	2		

DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)
Soft, grayish-brown, SILTY CLAY (continued) 395.8			
Very soft, gray, SILTY CLAY	0		
	1		40
	1		
392.3	0		
Medium dense to dense, light brown, FINE-GRAINED SAND -25	2		38
	7		
	7		
See Gradation Test Results	11		
	10		
	11		
-30	9		
	7		
	11		
	19		
-35	17		
379.8			
Medium dense, grayish-brown, MEDIUM-GRAINED SAND	9		
	10		
-40	12		

The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)
The SPT (N value) is the sum of the last two blow values in each sampling zone (AASHTO T206)
* Rimac attempted, not measured due to sample disturbance
** Not measured due to drilling methods used
BBS, from 137 (Rev. 8-99)

Illinois Department of Transportation
Division of Highways
Geotechnology, Inc

SOIL BORING LOG

Date 11/26/01

ROUTE FAP 998 DESCRIPTION Trilevel Interchange LOGGED BY JSS

SECTION 82-1 LOCATION East St. Louis, IL, SEC. 7, TWP. 2N, RNG. 9W

COUNTY St. Clair DRILLING METHOD HSA and Mud Rotary HAMMER TYPE Automatic Hammer

STRUCT. NO. 082-W306
Station

BORING NO. B-211
Station 67+60.43
Offset 8ft Right
Ground Surface Elev. 416.8 ft

Surface Water Elev. Unknown ft
Stream Bed Elev. Unknown ft

Groundwater Elev.:
First Encounter 397.8 ft ▼
Upon Completion ** ft
After ** Hrs. ** ft

DEPTH (ft)	BLOWS (/6")	UCS Qu (tsf)	MOIST (%)
Medium dense, grayish-brown, MEDIUM-GRAINED SAND (continued)			
	6		
See Attached Gradation Test Results	6		
-45	8		