


The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)  
 AASHTO Classifications are based on visual classifications unless otherwise noted BBS, form 137 (Rev. 8-99)



The Unconfined Compressive Strength (UCS) Failure Mode is indicated by (B-Bulge, S-Shear, P-Penetrometer)  
 AASHTO Classifications are based on visual classifications unless otherwise noted BBS, form 137 (Rev. 8-99)

REVISIONS
-----------

Esport Business Center I  
 100 Lantz Court, Suite 1  
 Collinsville, Illinois 62234  
 Phone: 618 345-2500  
 Fax: 618 345-7233  
 e-mail: info@scie.com  
 web-site: www.scie.com

**DAIES ASSOCIATES**  
 Consulting Engineers

ALTON, ILLINOIS  
 PEDESTRIAN OVERPASS AT LANGDON ST.

**BORING LOGS**  
**ALTON PEDESTRIAN WALKWAY OVER**  
**UNION PACIFIC RAILROAD, NORFOLK**  
**SOUTHERN RAILROAD AND US ROUTE 67**  
**SECTION 06-00224-00-BR**  
**MADISON COUNTY**  
**STA. 2+42.54**  
**STRUCTURE NO. 060-6111**

DWG. NO.	S24
6111-24-BORESHT2.DGN	
REF. BK.	PG.
JOB NO.	26053
DSN. BY:	NEL
DWN. BY:	NEL
CHK. BY:	JGS
DATE:	1/9/07
SCALE:	
SHEET	44 OF 54