

ACQUIRE NO.	SECTION	COUNTY	DATE	SHEET
E. 3150	*	BUREAU	15	11
FED. ROAD DIST. NO. 7	ALWAYS	FED. AID PROJECT		

Sheet 8  
of 9 Sheets

\* 04-04113-00-BR

<b>Midwest Testing Services, Inc.</b> 3705 Progress Blvd. Peru, IL 61354		<b>BORING LOG</b> Sheet <u>3</u> of <u>4</u>	Phone: 815-223-6696 Fax: 815-223-6659 E-Mail: Midwest@TheRamp.net																																																																																																	
Client: <u>Bureau County Highway Department</u> Project Name: <u>Section 04-04113-00-BR</u> Project Site: <u>Clarion Township</u>		Boring No. <u>B-2</u> Surface Elev. <u>99.80</u> Auger Depth <u>66'</u> Rotary Depth <u>NA</u> Start Date <u>02/05/05</u> Finish Date <u>02/05/05</u>																																																																																																		
Location: <u>2' Lt Station 20+40</u>																																																																																																				
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2">CAPSULE LOG</th> <th colspan="4">SAMPLES</th> <th>DRILLED BY</th> </tr> <tr> <th>Cap</th> <th>Log</th> <th>Sample No.</th> <th>Sample Type</th> <th>Qu (TSF)</th> <th>N Value (Blows)</th> <th>Bulge / Shear</th> <th>Moisture (%)</th> <th>Dry Density (PCF)</th> </tr> <tr> <td></td> <td></td> <td>17</td> <td>SS</td> <td>--</td> <td>14</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>18</td> <td>SS</td> <td>--</td> <td>17</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>19</td> <td>SS</td> <td>--</td> <td>17</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>20</td> <td>SS</td> <td>--</td> <td>18</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>21</td> <td>SS</td> <td>--</td> <td>16</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>22</td> <td>SS</td> <td>--</td> <td>15</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>23</td> <td>SS</td> <td>--</td> <td>19</td> <td>--</td> <td>--</td> <td></td> </tr> <tr> <td></td> <td></td> <td>24</td> <td>SS</td> <td>5.5</td> <td>32</td> <td>S</td> <td>10</td> <td></td> </tr> <tr> <td></td> <td></td> <td>25</td> <td>SS</td> <td>4.9</td> <td>25</td> <td>S</td> <td>11</td> <td></td> </tr> </table>	CAPSULE LOG		SAMPLES				DRILLED BY	Cap	Log	Sample No.	Sample Type	Qu (TSF)	N Value (Blows)	Bulge / Shear	Moisture (%)	Dry Density (PCF)			17	SS	--	14	--	--				18	SS	--	17	--	--				19	SS	--	17	--	--				20	SS	--	18	--	--				21	SS	--	16	--	--				22	SS	--	15	--	--				23	SS	--	19	--	--				24	SS	5.5	32	S	10				25	SS	4.9	25	S	11		DRILLED BY Randy Sfranski Diedrich D-120
CAPSULE LOG		SAMPLES				DRILLED BY																																																																																														
Cap	Log	Sample No.	Sample Type	Qu (TSF)	N Value (Blows)	Bulge / Shear	Moisture (%)	Dry Density (PCF)																																																																																												
		17	SS	--	14	--	--																																																																																													
		18	SS	--	17	--	--																																																																																													
		19	SS	--	17	--	--																																																																																													
		20	SS	--	18	--	--																																																																																													
		21	SS	--	16	--	--																																																																																													
		22	SS	--	15	--	--																																																																																													
		23	SS	--	19	--	--																																																																																													
		24	SS	5.5	32	S	10																																																																																													
		25	SS	4.9	25	S	11																																																																																													
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>(DEPTH) ELEV.</th> <th>DESCRIPTION OF MATERIALS</th> <th>DEPTH in feet</th> <th>REMARKS</th> </tr> <tr> <td>57.80</td> <td></td> <td></td> <td></td> </tr> <tr> <td>56.80</td> <td></td> <td>43</td> <td></td> </tr> <tr> <td>55.80</td> <td></td> <td>44</td> <td></td> </tr> <tr> <td>54.80</td> <td></td> <td>45</td> <td></td> </tr> <tr> <td>53.80</td> <td></td> <td>46</td> <td></td> </tr> <tr> <td>52.80</td> <td></td> <td>47</td> <td></td> </tr> <tr> <td>51.80</td> <td></td> <td>48</td> <td></td> </tr> <tr> <td>50.80</td> <td style="text-align: center;">Medium Gray Fine Sand With Occasional Coarse Gravel</td> <td>49</td> <td></td> </tr> <tr> <td>49.80</td> <td></td> <td>50</td> <td></td> </tr> <tr> <td>48.80</td> <td></td> <td>51</td> <td></td> </tr> <tr> <td>47.80</td> <td></td> <td>52</td> <td></td> </tr> <tr> <td>46.80</td> <td></td> <td>53</td> <td></td> </tr> <tr> <td>45.80</td> <td></td> <td>54</td> <td></td> </tr> <tr> <td>44.80</td> <td></td> <td>55</td> <td></td> </tr> <tr> <td>43.80</td> <td></td> <td>56</td> <td></td> </tr> <tr> <td>42.80</td> <td></td> <td>57</td> <td></td> </tr> <tr> <td>41.80</td> <td></td> <td>58</td> <td></td> </tr> <tr> <td>40.80</td> <td></td> <td>59</td> <td></td> </tr> <tr> <td>39.80</td> <td style="text-align: center;">Hard Pink To Gray Silty Clay Loam Till</td> <td>60</td> <td></td> </tr> <tr> <td>38.80</td> <td></td> <td>61</td> <td></td> </tr> <tr> <td>37.80</td> <td></td> <td>62</td> <td></td> </tr> </table>			(DEPTH) ELEV.	DESCRIPTION OF MATERIALS	DEPTH in feet	REMARKS	57.80				56.80		43		55.80		44		54.80		45		53.80		46		52.80		47		51.80		48		50.80	Medium Gray Fine Sand With Occasional Coarse Gravel	49		49.80		50		48.80		51		47.80		52		46.80		53		45.80		54		44.80		55		43.80		56		42.80		57		41.80		58		40.80		59		39.80	Hard Pink To Gray Silty Clay Loam Till	60		38.80		61		37.80		62									
(DEPTH) ELEV.	DESCRIPTION OF MATERIALS	DEPTH in feet	REMARKS																																																																																																	
57.80																																																																																																				
56.80		43																																																																																																		
55.80		44																																																																																																		
54.80		45																																																																																																		
53.80		46																																																																																																		
52.80		47																																																																																																		
51.80		48																																																																																																		
50.80	Medium Gray Fine Sand With Occasional Coarse Gravel	49																																																																																																		
49.80		50																																																																																																		
48.80		51																																																																																																		
47.80		52																																																																																																		
46.80		53																																																																																																		
45.80		54																																																																																																		
44.80		55																																																																																																		
43.80		56																																																																																																		
42.80		57																																																																																																		
41.80		58																																																																																																		
40.80		59																																																																																																		
39.80	Hard Pink To Gray Silty Clay Loam Till	60																																																																																																		
38.80		61																																																																																																		
37.80		62																																																																																																		
Groundwater Data: Static water level after auger removal - elevation 91.5 Comments:																																																																																																				

<b>Midwest Testing Services, Inc.</b> 3705 Progress Blvd. Peru, IL 61354		<b>BORING LOG</b> Sheet <u>4</u> of <u>4</u>	Phone: 815-223-6696 Fax: 815-223-6659 E-Mail: Midwest@TheRamp.net																																																																																										
Client: <u>Bureau County Highway Department</u> Project Name: <u>Section 04-04113-00-BR</u> Project Site: <u>Clarion Township</u>		Boring No. <u>B-2</u> Surface Elev. <u>99.80</u> Auger Depth <u>66'</u> Rotary Depth <u>NA</u> Start Date <u>02/05/05</u> Finish Date <u>02/05/05</u>																																																																																											
Location: <u>2' Lt Station 20+40</u>																																																																																													
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2">CAPSULE LOG</th> <th colspan="4">SAMPLES</th> <th>DRILLED BY</th> </tr> <tr> <th>Cap</th> <th>Log</th> <th>Sample No.</th> <th>Sample Type</th> <th>Qu (TSF)</th> <th>N Value (Blows)</th> <th>Bulge / Shear</th> <th>Moisture (%)</th> <th>Dry Density (PCF)</th> </tr> <tr> <td></td> <td></td> <td>25</td> <td>SS</td> <td>4.9</td> <td>25</td> <td>S</td> <td>11</td> <td></td> </tr> <tr> <td></td> <td></td> <td>26</td> <td>SS</td> <td>5.4</td> <td>33</td> <td>S</td> <td>10</td> <td></td> </tr> </table>	CAPSULE LOG		SAMPLES				DRILLED BY	Cap	Log	Sample No.	Sample Type	Qu (TSF)	N Value (Blows)	Bulge / Shear	Moisture (%)	Dry Density (PCF)			25	SS	4.9	25	S	11				26	SS	5.4	33	S	10		DRILLED BY Randy Sfranski Diedrich D-120																																																								
CAPSULE LOG		SAMPLES				DRILLED BY																																																																																							
Cap	Log	Sample No.	Sample Type	Qu (TSF)	N Value (Blows)	Bulge / Shear	Moisture (%)	Dry Density (PCF)																																																																																					
		25	SS	4.9	25	S	11																																																																																						
		26	SS	5.4	33	S	10																																																																																						
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>(DEPTH) ELEV.</th> <th>DESCRIPTION OF MATERIALS</th> <th>DEPTH in feet</th> <th>REMARKS</th> </tr> <tr> <td>36.80</td> <td></td> <td></td> <td></td> </tr> <tr> <td>35.80</td> <td style="text-align: center;">Hard Pink To Gray Silty Clay Loam Till</td> <td>64</td> <td></td> </tr> <tr> <td>34.80</td> <td></td> <td>65</td> <td></td> </tr> <tr> <td>33.80</td> <td></td> <td>66</td> <td></td> </tr> <tr> <td>32.80</td> <td style="text-align: center;">Bottom of Boring</td> <td>67</td> <td></td> </tr> <tr> <td>31.80</td> <td></td> <td>68</td> <td></td> </tr> <tr> <td>30.80</td> <td></td> <td>69</td> <td></td> </tr> <tr> <td>29.80</td> <td></td> <td>70</td> <td></td> </tr> <tr> <td>28.80</td> <td></td> <td>71</td> <td></td> </tr> <tr> <td>27.80</td> <td></td> <td>72</td> <td></td> </tr> <tr> <td>26.80</td> <td></td> <td>73</td> <td></td> </tr> <tr> <td>25.80</td> <td></td> <td>74</td> <td></td> </tr> <tr> <td>24.80</td> <td></td> <td>75</td> <td></td> </tr> <tr> <td>23.80</td> <td></td> <td>76</td> <td></td> </tr> <tr> <td>22.80</td> <td></td> <td>77</td> <td></td> </tr> <tr> <td>21.80</td> <td></td> <td>78</td> <td></td> </tr> <tr> <td>20.80</td> <td></td> <td>79</td> <td></td> </tr> <tr> <td>19.80</td> <td></td> <td>80</td> <td></td> </tr> <tr> <td>18.80</td> <td></td> <td>81</td> <td></td> </tr> <tr> <td>17.80</td> <td></td> <td>82</td> <td></td> </tr> <tr> <td>16.80</td> <td></td> <td>83</td> <td></td> </tr> </table>			(DEPTH) ELEV.	DESCRIPTION OF MATERIALS	DEPTH in feet	REMARKS	36.80				35.80	Hard Pink To Gray Silty Clay Loam Till	64		34.80		65		33.80		66		32.80	Bottom of Boring	67		31.80		68		30.80		69		29.80		70		28.80		71		27.80		72		26.80		73		25.80		74		24.80		75		23.80		76		22.80		77		21.80		78		20.80		79		19.80		80		18.80		81		17.80		82		16.80		83		
(DEPTH) ELEV.	DESCRIPTION OF MATERIALS	DEPTH in feet	REMARKS																																																																																										
36.80																																																																																													
35.80	Hard Pink To Gray Silty Clay Loam Till	64																																																																																											
34.80		65																																																																																											
33.80		66																																																																																											
32.80	Bottom of Boring	67																																																																																											
31.80		68																																																																																											
30.80		69																																																																																											
29.80		70																																																																																											
28.80		71																																																																																											
27.80		72																																																																																											
26.80		73																																																																																											
25.80		74																																																																																											
24.80		75																																																																																											
23.80		76																																																																																											
22.80		77																																																																																											
21.80		78																																																																																											
20.80		79																																																																																											
19.80		80																																																																																											
18.80		81																																																																																											
17.80		82																																																																																											
16.80		83																																																																																											
Groundwater Data: Static water level after auger removal - elevation 91.5 Comments:																																																																																													

ELEVATION 100.00 = 100.3  
 STATION 20+00 = 10+00

SOIL BORINGS  
 E. 3150 TH ROAD OVER PIKE CREEK  
 SECTION 04-04113-00-BR  
 BUREAU COUNTY  
 STA. 10+00  
 SN 006-4051