

BOLT HOLE DETAIL

DRAWN BECKY M. LEACH

CHECKED

JWM/GRA

8/1/2000

| UNIT QUANTITY | SECTION 3R(BR, BR-1, BR-2)19RS-8 |
| SANGAMON COUNTY |
| STATION 17+97.34 |
| STRUCTURE NO. 084-0518