



REPAIRS LIST - SPAN 10 (SOUTH HALF)

I.D.	Repair Description	Pay Item	Units	Quantity
044	Clogged Floor Drain	Cleaning Bridge Scuppers and Downspouts	Each	1
045	Clogged Scupper	Cleaning Bridge Scuppers and Downspouts	Each	1
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-
-	-	-	-	-

Repair I.D.
 OTHER ITEMS

DESIGNED -
 CHECKED -
 DRAWN Rod
 CHECKED MNM

EXAMINED _____ DATE -
 ENGINEER OF STRUCTURAL SERVICES

PASSED _____
 ENGINEER OF BRIDGES AND STRUCTURES

**STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION**

REPAIRS TO - CSS - DECK and PARAPETS - SPAN 10 (SO. HALF)
STRUCTURE NO. 060-0255

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
304	100B-1D5-1	MADISON	58	18
CONTRACT NO. 76E73				