


SOIL BORINGS

PROJECT **Box Culvert Replacement, Rockton Road over Dry Run Creek, Winn. Co., Illinois**
 CLIENT **Missman, Inc., Rockford, Illinois**
 BORING **2** DATE STARTED **8-8-12** DATE COMPLETED **8-8-12** JOB **L-78,847**
 ELEVATIONS WATER LEVEL OBSERVATIONS
 GROUND SURFACE **758.9** WHILE DRILLING **26.0'**
 END OF BORING **708.9** AT END OF BORING **31.0'**
 24 HOURS



PROJECT **Box Culvert Replacement, Rockton Road over Dry Run Creek, Winn. Co., Illinois**
 CLIENT **Missman, Inc., Rockford, Illinois**
 BORING **2** DATE STARTED **8-8-12** DATE COMPLETED **8-8-12** JOB **L-78,847**
 ELEVATIONS WATER LEVEL OBSERVATIONS
 GROUND SURFACE **758.9** WHILE DRILLING **26.0'**
 END OF BORING **708.9** AT END OF BORING **31.0'**
 24 HOURS

