



TYPICAL FIELD ENTRANCE
 3:1 OR FLATTER SIDE SLOPES
 LT., STA. 142+80
 RT., STA. 155+50



RIPRAP DETAIL AT EXISTING SUSPENDED CULVERT

