

GUTTERS SCHEDULE

STATIONING	REMARKS	X0320882 GUTTERS TO BE CLEANED FOOT	40800050 INCIDENTAL HMA SURFACE TON	44000400 GUTTER REMOVAL FOOT	X6062400 CONCRETE GUTTER (SPECIAL) FOOT
MAINLINE EASTBOUND					
39+36.00 - 40+16.00	BROKEN UNDER OLD IL 2	-	-	80.00	80.00
86+95.00 - 87+35.00	LOW UNDER 226TH ST	40.00	2.24		
183+30.00 - 183+78.00	LOW UNDER 248TH ST	48.00	3.58		
254+50.00 - 255+08.00	LOW UNDER 265TH ST	58.00	5.41		
300+91.00 - 302+01.00	LOW UNDER IL 92	110.00	5.13		
370+97.00 - 371+32.00	LOW UNDER 286TH ST	35.00	1.96		
435+88.00 - 436+28.00	LOW UNDER 66TH AVE	40.00	4.11		
560+04.00 - 560+61.00	LOW UNDER 94TH AVE	57.00	3.19		
705+39.00 - 706+03.00	LOW UNDER 112ND AVE	64.00	4.78		
MAINLINE WESTBOUND					
39+09.00 - 39+89.00	CLEANING UNDER OLD IL 2	80.00	-		
87+13.00 - 87+53.00	LOW UNDER 226TH ST	40.00	2.61		
183+31.00 - 183+79.00	LOW UNDER 248TH ST	48.00	0.90		
255+97.00 - 256+55.00	LOW UNDER 265TH ST	58.00	3.79		
299+35.00 - 300+45.00	LOW UNDER IL 92	110.00	7.19		
370+97.00 - 371+32.00	LOW UNDER 286TH ST	35.00	3.59		
435+88.00 - 436+28.00	LOW UNDER 66TH AVE	40.00	3.73		
540+96.00 - 541+93.00	LOW UNDER MOLINE RD	97.00	4.53		
560+28.00 - 560+85.00	LOW UNDER 94TH AVE	57.00	3.19		
633+90.00 - 634+28.00	LOW UNDER 317 TH ST	38.00	2.13		
703+50.00 - 704+14.00	LOW UNDER 112ND AVE	64.00	6.57		
TOTAL:		1119.00	68.64	80.00	80.00